



BILL TO Paula Swaggerty 479 Eagle Brook Ct Debary, FL 32713	JOB SITE Paula Swaggerty 479 Eagle Brook Ct Debary, FL 32713	BALANCE DUE	
DESCRIPTION OF WORK	QUANTITY	PRICE	TOTAL
 Staple Crack (3-5 feet) Check underground water tables Drain water enough to perform repara Repair crack with staple(s) Patch surface (see patch disclaimendetails) 1 year warranty included Structural cracks in pools/spas can be of by any number of factors, including gromovement, poor construction, and/or neglected leak issues that have over timundermined the pool/spa deck's foundational issues that have over timundermined the pool/spa deck's foundational issues that have over the underlying foundational issues that shell only. We cannot measure the extension of the existing cracked areas in the shell only. We cannot measure the extension of the existing cracks to develop in other areas, or cauthe existing cracks to extend and reopereven after our repair. In the rare event our crack repair leaks within the warrant period, we will make one more attempt reinforce and seal it. Also, it should be known that in some instances, we may discover (after starting compromised around the cracked areas cannot be properly reinforced and seal (i.e. Just imagine trying to hold sand or seal of the starting cracked areas). 	1 ir for caused und ne tion. inforce he pool ent of od that causing using using using using using that ty to ng the that it ed as is	\$1,495.00	\$1,495.00



immediately notified and advised to work directly with a pool builder to demo and re- pour that section of pool wall. Discount	1	(\$1,495.00)	(\$1,495.00)
		Subtotal:	\$0.00
		Tax:	\$0.00
		Payments:	\$0.00
	E	Balance Due:	\$0.00

Payment History

DATE	PAYMENT TYPE	STATUS	DESCRIPTION	NOTES	AMOUNT

Results & Findings

💟 Tuesday, November 30, 2021 appointment

Findings

Repair completed. Water level is half empty Pool can be filled immediately Pump is off at the timer Valves were readjusted to their original positions



The Pool Leak Experts



Warranties & Disclaimers

Payment is expected at time of service. License #CPC1457457

Note:

If any of our quoted repairs are completed by another company, our leak detection warranty will be voided. A separate fee will be charged if further testing is requested.

Customer is responsible for refilling water and balancing chemicals. Please monitor water levels for 48 hours. Contact RRLD with any questions or concerns.

Change Order Disclaimer:

A change order will be issued if RRLD discovers any unforeseen or unexpected work not specified above. An additional quote will be issued at that time.

Deck Disclaimer:

RRLD does not offer custom staining or textures. We will make every attempt to match the deck when applying deck patches. If an exact match is desired (color and texture), customer will need to hire a professional deck company to apply the patch.

Patch Disclaimer:

Red Rhino Leak Detection (RRLD) will make every attempt to match the existing surface when applying patches. However, due to variations of the product from the manufacturer and aging of the existing surface, it is impossible to achieve an exact match when patching. Refinishing the entire surface is the only way to ensure a consistent appearance without variation. Therefore, RRLD cannot be held responsible for color and texture variations which are unavoidable when patching.



Sign Invoice

Please sign and date below for approval and return via email(redrhinocsr@redrhino.com) or fax(561-692-4814). All scheduling is on a first come first serve basis. We will contact you regarding scheduling upon receipt of the signed document

Х

Date

Printed Name