



## Results & Findings

☒ Monday, July 12, 2021 appointment

### Leaks

Found broken skimmer line under the deck. Marked deck with photo. Needs to be repaired. Plugged off skimmer pipe and shut off at valve to prevent further water loss.



### Miscellaneous

☒ Wednesday, May 19, 2021 appointment

### Leaks

Found leak around pool return. Patched with epoxy. Recommend proper repair.



## Equipment

Description of deck and surface. Deck: Pavers Surface: Brown/Gold Pebble Tech  
Picture of pool equipment.



## Miscellaneous

Pipe labeled main drain on pool pump may actually be a waste line. Didn't purge air into pool.



### Test Related

Pressure tested all lines. All lines appear to be holding solid. Unable to pressure test far left pump (cleaner). Dye tested floor returns, held solid.