

## Results & Findings


📅 Wednesday, September 29, 2021 appointment

### Leaks

Found leak around pool return. Patched with epoxy. Recommend proper repair.




Found leak in skimmer throat where the plastic skimmer butts up to the cement pool shell. Patched with epoxy. Recommend proper repair.



## Equipment

Description of deck and surface.

Deck: Travertine Pavers Surface: Bone Gem Picture of pool equipment.



Found air leak at valve. When pump is running, air is entering through the skimmer Jandy valve needs to be serviced. See picture for dysfunctional valve.



Found air leak at suction side elbow. When pump is running, air is entering the system through elbow. Fittings need to be replaced. See picture for dysfunctional fitting.



### Pool Status

Epoxy was applied as a temporary patch to the leaking skimmer throat and pool return so that it can be ensured all leaks have been identified and all appropriate repairs have been quoted.

### Test Related

Pressure tested all lines. All lines appear to be holding solid.

