

**RED RHINO®****The Pool Leak  
Experts**

Issued: 10/15/2022 Due: 10/15/2022 Invoice #286276

# Invoice

## BILL TO

**Connie Hudson**2903 Banyan Boulevard Cir  
NW  
Boca Raton, FL 33431

## JOB SITE

**Connie Hudson**2903 Banyan Boulevard Cir  
Boca Raton, FL 33431

## BALANCE DUE

**\$0.00**

DESCRIPTION OF WORK	QUANTITY	PRICE	TOTAL
<b>Residential Pool Leak Detection</b>	1	\$350.00	\$350.00

- Includes testing of the pool shell, plumbing lines and equipment
- 60 day warranty
- If proper repairs are scheduled within 7 days of the initial leak detection, a \$100 scheduling discount will be applied to the repair invoice

*Note: Bodies of water can lose up to a 1/4 inch a day from evaporation under normal operating conditions.*

*Disclaimer: Fees for services will apply if water loss is due to evaporation.*

Subtotal:	<b>\$350.00</b>
Tax:	<b>\$0.00</b>
Payments:	<b>\$350.00</b>

**Balance Due: \$0.00**

## Payment History

DATE	PAYMENT TYPE	STATUS	CC LAST FOUR	DESCRIPTION	NOTES	AMOUNT
------	--------------	--------	--------------	-------------	-------	--------

**RED RHINO®****The Pool Leak  
Experts**

Issued: 10/15/2022 Due: 10/15/2022 Invoice #286276

Feb 15, 2024 Credit Card Paid 4880

\$350.00

## Results & Findings




Saturday, October 15, 2022 appointment

We checked your entire setup and we found some leaks that need to be properly repaired.

### Leaks

Found leak in skimmer throat where the plastic skimmer butts up to the cement pool shell. Patched with epoxy. Recommend proper repair.



Found leak around overflow line. Patched with epoxy. Plugged overflow line as requested, as it sits too low in the pool.



### Pool Status

**Deck:**Pavers

**Surface:**

Capri



Epoxy was applied as a temporary patch to the leaking area(s) so that it can be ensured all leaks have been identified and all appropriate repairs have been quoted.

### Test Related

Tested all lines. All lines appear to be holding solid.

**RHINO**<sup>®</sup>**The Pool Leak  
Experts**

Issued: 10/15/2022 Due: 10/15/2022 Invoice #286276

Performed a complete dye test in the pool. Everything appears to be solid besides the skimmer throat.

## Warranties & Disclaimers

Payment is expected at time of service. License **#CPC1457457**

**Note:**

Customer is responsible for refilling water and balancing chemicals. Please monitor water levels for 48 hours. Contact RRLD with any questions or concerns.

**Change Order Disclaimer:**

A change order will be issued if RRLD discovers any unforeseen or unexpected work not specified above. An additional quote will be issued at that time.

**Deck Disclaimer:**

RRLD does not offer custom staining or textures. We will make every attempt to match the deck when applying deck patches. If an exact match is desired (color and texture), customer will need to hire a professional deck company to apply the patch.

**Patch Disclaimer:**

Red Rhino Leak Detection (RRLD) will make every attempt to match the existing surface when applying patches. However, due to variations of the product from the manufacturer and aging of the existing surface, it is impossible to achieve an exact match when patching. Refinishing the entire surface is the only way to ensure a consistent appearance without variation. Therefore, RRLD cannot be held responsible for color and texture variations which are unavoidable when patching.

## Sign Invoice



**RHINO**<sup>®</sup>

The Pool Leak  
Experts

Issued: 10/15/2022 Due: 10/15/2022 Invoice #286276

---

Please sign and date below for approval and return via email([redrhinocsr@redrhino.com](mailto:redrhinocsr@redrhino.com)) or fax(561-692-4814). All scheduling is on a first come first serve basis. We will contact you regarding scheduling upon receipt of the signed document

X

*Date*

*Printed Name*