

---

## Results & Findings

☒ Thursday, May 15, 2025 appointment

### Pool Status

Confirmed water level is holding solid. The pool is not leaking. Evaporation and equipment leak.



☒ Wednesday, May 14, 2025 appointment

## Areas of Concern

### Found existing epoxy patch:

- In and around the light
- Around the return
- In the tile
- In and around the vac line

Epoxy patches can be an indication of previous leaks that could open up in the future, initiating further water loss.

Epoxy patches are an indication of previous leaks that could open up in the future as the patch wears away, initiating further water loss. Recommend proper repair.

### Additional Notes:

Wall port closed with Epoxy




## Equipment

**Deck:**Pavers

**Surface:**

Pebble tec



## Miscellaneous



## Pool Status

The equipment will leak, as identified in the findings, until it is fixed by a pool service professional.





### Test Related


Performed a complete dye test.



**All lines are holding solid**

### Additional Notes:

Alternative testing on all returns Passed




**Water level marked in:** Zero

**Results will be confirmed by:** Phone call


**Date of confirmation:** 2025-05-15

**Additional Notes:**

Pump off



Pool Water Level



Bucket Water Level



Pool Water Level



Pool Water Level