

**RED RHINO**®The Pool Leak
Experts

Issued: 2/2/2022

Due: 2/2/2022

Invoice: #239537

Invoice

BILL TO

Paula Swaggerty
479 Eagle Brook Ct
Debary, FL 32713

JOB SITE

Paula Swaggerty
479 Eagle Brook Ct
Debary, FL 32713

BALANCE DUE

\$0.00

DESCRIPTION OF WORK	QUANTITY	PRICE	TOTAL
Discount	1	(\$1,340.00)	(\$1,340.00)
Fill In Pop Up <ul style="list-style-type: none">• Check underground water tables• Drain pool or spa completely• Chip out area and cut out pipe• Fill in area with cement• Patch surface (see patch disclaimer for details)• 1 year warranty included	2	\$895.00	\$1,790.00
Additional Break in the Yard – Discounted Rate <i>Disclaimer: Discounted pricing only applies if these repairs are performed at the same time as the other repairs.</i>	1	\$250.00	\$250.00

Subtotal: **\$700.00**Tax: **\$0.00**Payments: **\$700.00****Balance Due: \$0.00**



Payment History

DATE	PAYMENT TYPE	STATUS	CHECK #	DESCRIPTION	NOTES	AMOUNT
Feb 15, 2024	Check		1955	Check Payment		\$700.00

Results & Findings



Wednesday, February 2, 2022 appointment

Miscellaneous

Customer is having the pool resurfaced very shortly so the specialist was instructed to leave the cleanout plug removed to allow the water tables to relive up into the pool.

Findings

Repair completed. Water level is empty Pool can be filled immediately Pump is off at the breaker Valves were readjusted to their original positions

**RED RHINO®****The Pool Leak
Experts**

Issued: 2/2/2022 Due: 2/2/2022 Invoice: #239537



Warranties & Disclaimers

Payment is expected at time of service. License **#CPC1457457**

Note:

If any of our quoted repairs are completed by another company, our leak detection warranty will be voided. A separate fee will be charged if further testing is requested.

Customer is responsible for refilling water and balancing chemicals. Please monitor water levels for 48 hours. Contact RRLD with any questions or concerns.

Change Order Disclaimer:

A change order will be issued if RRLD discovers any unforeseen or unexpected work not specified above. An additional quote will be issued at that time.

Deck Disclaimer:

RRLD does not offer custom staining or textures. We will make every attempt to match the deck when applying deck patches. If an exact match is desired (color and texture), customer will need to hire a professional deck company to apply the patch.

Patch Disclaimer:

Red Rhino Leak Detection (RRLD) will make every attempt to match the existing surface when applying patches. However, due to variations of the product from the manufacturer and aging of the existing surface, it is impossible to achieve an exact match when patching. Refinishing the entire surface is the only way to ensure a consistent appearance without variation. Therefore, RRLD cannot be held responsible for color and texture variations which are unavoidable when patching.



RED RHINO®

The Pool Leak
Experts

Issued: 2/2/2022 Due: 2/2/2022 Invoice: #239537

Sign Invoice

Please sign and date below for approval and return via email(redrhinocsr@redrhino.com) or fax(561-692-4814). All scheduling is on a first come first serve basis. We will contact you regarding scheduling upon receipt of the signed document

X

Date

Printed Name
